

Work Order

Location: Main

Supervisor: Main

Equipment ID: F300-V

Work Order #:

Description: Ford 300 Pickup

Recurring:

Scheduled Date: 08/01/2004

Miles/Hrs: 0

Interval:

Repair Type: Repairs

Quantity: 0

Repair Notes: Need to fix tail light on passenger side

Completed By: _____

Completion Date: _____

Work Notes:

Parts Already Listed on the work order

<u>Part</u>	<u>Part Number</u>	<u>Vendor</u>	<u>Invoice #</u>	<u>Qty</u>	<u>Cost</u>	<u>Ext.</u>
Tail Light	56723456	Auto Parts	32154	1	\$46.95	\$46.95
Total Parts Cost:						\$46.95

Additional Parts used on this work order

<u>Part</u>	<u>Part Number</u>	<u>Vendor</u>	<u>Invoice #</u>	<u>Qty</u>	<u>Cost</u>
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____

Completion Notes:

If you need additional space please make notes on the other side of this sheet