

## Equipment Maintenance Completed Detail

04-Jul-19

Equipment ID: F300-V

Ford 300 Pickup 1

Location: Office

Supervisor: Main Supervisor

S. Date	Repair Type	Repair Description	Odometer Reading						
12/01/2018	Engine light	Replace Faulty Feul Cap, Check Fluids and rotate tires	35214						
<b>Completion Date</b>	01/15/2019	<b>Completed By</b> Tom Jones							
<b>Comp. Notes</b> Also Checked Fluids and Rotated Tires									
<u>Part</u>	<u>Part Number</u>	<u>Vendor</u>	<u>Invoice #</u>	<u>Qty</u>	<u>Unit Cost</u>	<u>Ext. Cost</u>			
Feul Cap	32515	Auto Parts Store	32595	1	\$54.00	\$54.00			
<b>Hrs:</b>	0.5	<b>Rate:</b>	\$60.00	<b>Labor Cost:</b>	\$30.00	<b>Other:</b>	\$5.04	<b>Parts Cost:</b>	\$54.00
<b>Repair Total Cost:</b>								<b>\$89.04</b>	